# NEW REPAIR & SYSTEM TEST CAPABILITY
Allen Bradley 1785-5/series PLC
Technical Bulletin

PLC 5 processor controlling multiple I/O racks.

K+S is able to repair all PLC-5 processors series A-D, excluding Ethernet. All processors are tested on a 12 station data highway network and are thoroughly tested in heat sealed enclosures. We have a very extensive repair procedure which includes complete preventive maintenance.

These processors are used extensively in industry and can be found in many industrial based facilities**.**

12 Month In-Service Warranty	All Units Are System Tested	No Charge Evaluation